



# Five Bow

Installation Instructions



**LIGHT FORMS**

Linear



Surface Mount

## Safety & Warning!


1. Read all instructions carefully.
2. All the installation must be completed by a qualified electrician.
3. Install in accordance with national and local electrical code regulations.
4. Turn off electrical power before installing or servicing fixture in any way.
5. Install only at dry areas.
6. To reduce the risk of fire and overheating, make sure all connections to be done properly.

# Five Bow


LIGHT FORMS

## Installation Instructions

### Luminaire Overview



### Accessories for Surface Mount




# Five Bow

## Installation Instructions



1. Turn off the main electrical supply from the fuse box before proceeding the installation process.

2(A). Mark and drill the location of the key holes on the ceiling.

2(B). Remove diffuser & heat sink from the fixture.




3. Fix the fixture on the ceiling with the help of screws.




## LIGHT FORMS

4(A). Reinstall the heat sink and diffuser into the fixture.

4(B) Make all the necessary electrical wire connections.



5. For joining multiple sections, use connectors and allen key screws as per the arrangement provided.



6. Wiring Diagram (non-dim and dim).


Non Dimmable (ON/OFF)




Switch Dimming



DALI Dimming



1-10V Dimming



7. Turn on power.